IA #\_\_\_\_\_\_

## .CONTAMINATION POTENTIAL

(MANUAL FOR EVALUATING CONTAMINATION POTENTIAL OF SURFACE IMPOUNDMENTS)

ORIGINAL (Red)

NAME/LOCATION PIGEON POINT LANDFILL	(Red)
ADDRESS NEW CASTLE CO; DEL.	
NPDES# SIC 28/9 + 2869 LAT 39° 42'	- LONG. 75° 32′
THE CONTAMINATION POTENTIAL IS LOW MODERATE HIGH VERY H	IGH AREA
UNSATURATED ZONE 7°-B WATER QUALITY 5-B GROUNDWATER AVAILAB	ILITY 4°+B
HAZARD OF CONTAMINANT 9-A TOTAL GROUNDWATER CONTAMINATION PO	OTENTIAL 25
ENDANGERMENT TO CURRENT WATER SUPPLIES 68-B MONITORING WELLS	s a
EQUENCY OF MONITORING SIGNIFICANT CHANGES IN GROUNDI	WATER
ADVERSELY  HILMINGTON PIGEON POINT SANITARY LANGFILL, PIGEON PO  SITE IS NOT LOCATED ON PROPERTY OF CHEMICAL PLANT PARTICIPAT BEEN USED FOR DISPOSAL FROM 1959 TO 1979. AT TIME OF USE, SITE BEING USED, CHEMICAL COMPONENTS OF MASTE DISPOSED AT THIS SITE	ING IN SURVEY, BUT IS KNOWN TO HAVE

References: Geologic Map No.4-"Geology of the Wilimington Area, Delaware, & "The Availability of Ground Water in New Castle County, Delaware.

The site is underlain by the Columbia Formation, which includes gravelly coarse and medium sands, and the Potmac Formation, which consists of silts and clays containing interbedded sands. The water table is about 5 feet from the surface and the saturation is approximately 200 feet thick.

Groundwater is expected to flow in the direction of the Delaware River. The water is generally excellent in quality.

The hazard of contaminant rating is based on the SIC codes, Industrial Inorganic and Organic Chemicals, and the Waste Identification Numbers, 2101-3, Metals Acids, Bases, and Salts.

There do not appear to be any water supply wells, injection wells, or surface impoundments, in the vicinity of the site.

SEMS DociD 2330207

Prepared By:

Date: November 17, 1980

Robert Allen 3AH30
Bruce Smith 3SA30
Abraham Ferdas 3EN10
Benjamin A. Lacy 3WA32